

# Futurecom Repeater Configurator (FRC)

## Release 1.24 – Release Notes

FRC Software (6A083X06):

New Version:1.24

Old Version: 1.22

**Note:** FRC 1.24 software supports all hardware platforms: PDR8000®, VRX1000, DVR, DVR-LX® and replaces existing FRC 1.22.

FRC 1.24 contains three main components to service all hardware programming needs

1. Configurator for APX Repeaters (VRX1000, DVR and DVR-LX®), ver. 2.22
2. Configurator for PDR8000®, ver. 4.11
3. Flash Downloader Utility, ver. 2.00

**FRC is compatible with following Futurecom Firmware Versions:**

This release of FRC is **backwards compatible with all repeater firmware versions**. It supports reading all previously configured devices.

To access new features/enhancements/improvements listed below, the repeater must be using applicable firmware version as identified in compatibility chart.

Firmware Compatibility Chart is located on the Futurecom Website in the Support Portal:

<https://www.futurecom.com/support/documentation-software/dvrs-vrx1000-apx/>

### New Features / Enhancements:

- Improve clarity of error messages when loading license file that has already been applied. <sup>DVR-513</sup>
- Aligned Feature License name with our official names in Ordering Guide. <sup>DVR-545</sup>
- Added warnings when reading/writing live data, DPD or DCD files if FM deviation values are low. <sup>DVR-552</sup>
- Changed "EPR Files" in menu to "EPR Files (Futurecom Support)". <sup>DVR-550</sup>
- Added Copy Data feature for Repeater Channel screen.
- Renamed "Legacy PSU Compatibility Mode Enabled" to "Legacy PSU Compatibility Mode"
- DCD file can be upgraded with license option file.
- Renamed OTAP Setup screen to Update Info and display the screen at all times

### Issues Fixed in This Release

- Fixed issue where single band FM deviation value was incorrectly halved when loading old DPD files. <sup>DVR-552</sup>
- Fixed Talkgroup ID out of range error message being off by 1 for the start of the range.
- Fixed loaded DCDs displaying incorrect serial numbers when re-saving.
- RSSI for monitoring window may not be displayed properly – fixed.
- Fixed VR Common setup window causing invisible error. <sup>DVR-537</sup>

### Reminder

**Creation or modification of DCD should be done after a repeater is read.**