

APX P25 Interfaced DVR/VRX1000 Firmware Release 1.62 – Release Notes

	New Version	Old Version
DVR/VRX1000 Application Software (4C083X11):	1.62	1.61
DVR/VRX1000 Boot Firmware (4C083X02):	1.60	1.60
DVR/VRX1000 BB DSP (4C083x04):	1.42	1.42
DVR TR DSP (4C083x03):	1.18	1.18
VRX1000 TR DSP (4C087x05):	1.07	1.07
Futurecom Repeater Configurator Software (6A083X06):	1.00	

Note: New firmware and FRC software is supporting all hardware platforms - VRX1000, DVR and DVR-LX.

Compatible with following Motorola Radio Firmware Versions:

DVR	APX4000/6000/6500/7000/7500/8000/8500	R21.40.00 or later
DVR-LX	APX4000/6000/6500/7000/7500/8000/8500	R21.40.00 or later
VRX1000	APX2500/4000/4500/5500/6000/6500/7000/7500/8000/8500	R21.40.00 or later

New Features / Enhancements:

- Futurecom Repeater Configurator (FRC)**
FRC is our unified configurator for all of Futurecom’s RF coverage solutions: DVR, VRX1000 and PDR8000®, including the recently announced DVR-LX. It’s a direct replacement to APX Tweaker and backward compatible to previous releases. All the U/I & command line supports remain identical.
- Enhanced DVRS Mode Switching from Local PSU-** refer to FRC Release Notes for further details

Issues fixed in this release:

- PSU SCAN feature:** Very poor performance (50% failure) of Rekey Request when SCAN is enabled and active on Local PSU (DVR-367)

Known issues in Firmware Release 1.62:

- None.