

PDR8000 Release 2.01

Product Tested:

Repeater Module Firmware 4C088X01: R2.01

IF Module Firmware 4C088X05: R2.00

Tested With:

PSU Type: APX7000 PSU Firmware: D15.71.55

Modems: Motorola UDS V.3225, Motorola Codex 3260 Fast Data Modem

GCM 8000 Comparator: CvCM_R07.17.005

New Performance Enhancements:

Description: This is a firmware update release 2.01 applicable to PDR8000 Portable Digital Repeater R2.0 or newer. It contains the following performance enhancement:

FEATURE	DESCRIPTION
OTAR Operation	Optimization for the time it takes to rekey portable over the air as on some cellular networks, it was taking longer than expected.

Known PDR8000 Issues in Release 2.01:

None

Known PDR8000 Limitations:

None



Subscribe to our newsletter if you want to be informed about new releases and updates.
Please visit <http://futurecom.com/support/newsletter/>